

Revision List
referred to on Certificate No.: 01/205/5834.00/21
Product Tested: Safety Function “Safe Torque Off” (STO)

SV2A series AC motor drive with STO function

Model Number	HW Revision	FW Revision*	Report-No.:	Certification Status
SV2A-2040 SV2A-2070 SV2A-2150	2945370300	V 1.00.03 (STO diagnostic library checksum: 0xB87D6477)	968/FSP 2215.00/21	<i>Valid</i>
SV2A-2200 SV2A-2300 SV2A-2550 SV2A-2750 SV2A-2F00	2945370400	V 1.00.03 (STO diagnostic library checksum: 0xB87D6477)	968/FSP 2215.00/21	<i>Valid</i>

Notes *: The software is not involved in the implementation of STO function, but performs part of diagnostic function on the STO circuitry only.

The content of this revision list has been agreed between manufacturer and Certification Body.

Revision:

Date	Rev.	Description / Changes	Author
2021-03-10	1.0	Initial creation, based on Report-No.: 968/FSP 2215.00/21	TÜV-kg