



Revision List

Reference to Certificate No.: 968/EZ 323.05/18

Product Tested: 3500/33 and /32M Relay Controller
Modules with 3500/33 or /32 Relay Output Modules



Safety related modules / components

Type Designation	Description	HW / FW Revision	Report-No.:	Certification Status
3500/32M_SIL1	3500/32M SIL1 4-Channel Relay Module	H / 3.3	968/EZ 323.04/16	<i>valid</i>
3500/32M_SIL2	3500/32M SIL2 4-Channel Relay Module	E / 3.3	968/EZ 323.04/16	<i>valid</i>
3500/32M_SIL1-A01-BXX	3500/32M SIL1 4-Channel Relay I/O Module	A / N/A	968/EZ 323.05/18	<i>valid</i>
3500/32M_SIL2-A01-BXX	3500/32M SIL2 4-Channel Relay I/O Module	A / N/A	968/EZ 323.05/18	<i>valid</i>
3500/33_SIL1	3500/33 SIL1 16-Channel Relay Module	H / 3.3	968/EZ 323.04/16	<i>valid</i>
3500/33_SIL2	3500/33 SIL2 16-Channel Relay Module	F / 3.3	968/EZ 323.04/16	<i>valid</i>
3500/33_SIL1-A01-BXX	3500/33 SIL1 16-Channel Relay I/O Module	P / N/A	968/EZ 323.05/18	<i>valid</i>
3500/33_SIL2-A01-BXX	3500/33 SIL2 16-Channel Relay I/O Module	P / N/A	968/EZ 323.05/18	<i>valid</i>
3500/33_SIL1-A02-BXX	3500/33 SIL1 16-Channel Relay Failsafe I/O Module	F / N/A	968/EZ 323.05/18	<i>valid</i>
3500/33_SIL2-A02-BXX	3500/33 SIL2 16-Channel Relay Failsafe I/O Module	F / N/A	968/EZ 323.05/18	<i>valid</i>
3500/33_SIL1-A03-BXX	3500/33 SIL1 Low Current 16-Channel Relay I/O Module	B / N/A	968/EZ 323.05/18	<i>valid</i>
3500/33_SIL2-A03-BXX	3500/33 SIL2 Low Current 16-Channel Relay I/O Module	B / N/A	968/EZ 323.05/18	<i>valid</i>
3500/33_SIL1-A04-BXX	3500/33 SIL1 Low Current 16-Channel Relay Failsafe Relay I/O Module	A / N/A	968/EZ 323.05/18	<i>valid</i>
3500/33_SIL2-A04-BXX	3500/33 SIL2 Low Current 16-Channel Relay Failsafe Relay I/O Module	A / N/A	968/EZ 323.05/18	<i>valid</i>

XX = 00, 01 or 02

The revision list was agreed between the manufacturer and the Test Institute.

BENTLY NEVADA Inc.
1631 Bently Parkway South
Minden, NV 89423
United States of America

TÜV Rheinland Industrie Service GmbH
Automation - Functional Safety (A-FS)
Am Grauen Stein
51105 Köln / Germany





Revision List

Reference to Certificate No.: 968/EZ 323.05/18
Product Tested: 3500/33 and /32M Relay Controller
Modules with 3500/33 or /32 Relay Output Modules



Revision_List_Template_engl.docx Rev. v1.0

	Released by Test Institute:	Released by Specialist Certifier:
Signatures: <i>Sanjay Bhakeerathan</i>	 M.Sc. Marcel Gruschka	 Dipl.-Ing. Gebhard Bouwer
Date: 2018-07-20	2018-08-14	2018-08-14

Revision:

Date	Rev.	Description / Changes	Author
2016-09-12	1.0	Initial creation, based on Report-No.: 968/EZ 323.04/16	hay/A-FS
2018-08-14	1.1	Enhanced by new safety related modules, based on Report-No.: 968/EZ 323.05/18	mgu/A-FS