



Module List Standard Safety ACOPOSmotor

Datum: 03. April 2018

We reserve the right to change the content of this manual without prior notice. The information contained herein is believed to be accurate as of the date of publication, however, B&R makes no warranty, expressed or implied, with regards to the products or the documentation contained within this document. B&R shall not be liable in the event of incidental or consequential damages in connection with or arising from the furnishing, performance or use of these products. The software names, hardware names and trademarks used in this document are registered by the respective companies.

I Versions

Version	Datum	Kommentar	Bearbeiter
1.0	12.07.2013	First Edition	Roland Scharinger
2.0	11.02.2015	Update version of user's manual	Rupert Posch
3.0	03.04.2018	Update of HW revisions Update of listed devices Update version of user's manual	Sonja Heindl

Tabelle 1: Versions

II Table of Contents

1 Motivation	3
2 Overview of the devices	3
3 Release	3

1 Motivation

The devices to be listed on the ACOPOSmotor safe pulse disabling certificate must be specified.




2 Overview of the devices

The safety circuit is designed identically on all of the following types.

	Product Type	Description	Hardware Revision		Software Revision	
			From	To		
ACOPOSmotor Configuration 8DI3x0.xxxxxxxxx-1, 8DI4x0.xxxxxxxxx-1, 8DI5x0.xxxxxxxxx-1						
ACOPOSmotor gearbox configuration 8Gxxx-LMA3x-xxxxx, 8Gxxx-LMA4x-xxxxx, 8Gxxx-LMA5x-xxxxx						
upper part 1	8ZDI0000HCS0.008-1	ACPM65m OT Br	Rev. C0	Rev. F0	- ¹	- ¹
upper part 2	8ZDI0000HCS0.00F-1	ACPM65m OT Br PLK 24Vout Tr	Rev. C0	Rev. F0	- ¹	- ¹
Lower part	8ZDI5000HCS0.000-1	ACPM65m UT 50A	Rev. C0	Rev. D0	- ¹	- ¹

Dokumentation			
MAACPMDE-GER	Distributed Drive Systems user's manual – German	Version 0.30	Version 0.40
MAACPMDE-ENG	Distributed Drive Systems user's manual – English	Version 0.30	Version 0.40

3 Release

	Manufacturer	Test Institute	Certifier
Signatures			
Date	05.07.2018	21.08.2018	21.08.2018

¹ Not safety relevant

